To: Matt Francis[m.francis@erllc.com]; Jacob Greenman[jgreenman@harwest.com]
Cc: Chris Hassel[CHassel@harwest.com]; Way, Steven[way.steven@epa.gov]; Christoph

Goss[christoph.goss@deereault.com]; Petri, Elliott[Elliott.Petri@WestonSolutions.com]

From: Bob Heeter

**Sent:** Wed 9/23/2015 10:07:01 PM

Subject: RE: Inside shotcrete

We have sent the request for a change in volume of the non fiber shotcrete, have not got an answer back yet and hope we have gotten them the request in time.

From: Matt Francis [m.francis@erllc.com]

Sent: Wednesday, September 23, 2015 4:10 PM

To: Bob Heeter; Jacob Greenman

Cc: Chris Hassel; Way, Steven; Christoph Goss; Petri, Elliott

Subject: Inside shotcrete

Christoph calculated the amount of shotcrete needed to cover the cathedral areas inside the Gold King at 15cy. This calculation was based on a 2" application of shotcrete (no fibers) from the spring line upward. He understands that it is likely that not all of the steel mesh will be covered with a 2" application. Shotcrete in this area is not intended to be the final support, so a thicker application is not required. Please revise the shotcrete order to accommodate the 15cy as necessary. Thanks

Matt Francis
Environmental Restoration, LLC
303.994.6611

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.